



# CHANGE!



Some of SS remain "JAPAN"


<http://www.newera.co.jp/>

**New-Era Co., Ltd.**



## INFORMATION

# IVR-942 now STRONGER !!!



## Additional functions

### IVR-942

MD619167  
TF35-18-W70  
23215-K8470  
(A866X24472)  
RFG1-18-W70  
(A866X24972)  
MD618735  
(A866X25572)

① Over-current Protection

② Short-circuit Protection

Same applications as Page 101 of 2009 Catalogue.

## DISCONTINUED PRODUCTS

SS-1611	Starter Solenoid
SS-1669	Starter Solenoid
B-18	Speed Control Unit
B-19	Drive Screw