

AVR-615EX NEW DESIGN!!

- 【Features】**
- ① Protection against short circuit of rotor coil.
 - ② Protection against reverse connection.
 - ③ Protection against short circuit of charge lamp.
 - ④ Protection against over voltage.




Connector ASSY & Installation dimensions are same as AVR-615.

5A mini blade fuse will protect circuit of AVR-615EX from over current by bad condition rotor coil and protect against reverse connection.

High hardness and High weatherability body.

High Performance Regulator




Illustration	Ref. No.	Application	On Sale
<p>AVR-615EX 24V</p> 	9-8225-0129-0	<p>ISUZU TRUCK TX,TWS(DA 640) '78~'81 SFR(DA640) '76~ TD,SLR(DH100)SPM,TKM(E120) '76~ BUS CCM,ECM(6BD1) '80~ CLM,CLA(DH100H) '80~ CJM,CJA(6QA2) '80~'81 CPM,CPA(E120H) '80~'81 BU-K(E120H) '76~'78 BH(8MA1),CRA(10PA1) '76~ TRUCK SKW(8PA1) '76~'84 SK,SM(8PB1) '80~'84 SRM,VRR(10PA1) '76~ SSZ,SSK,VSR(10PB1) '80~ SSH,SSZ,SSK,VSR(10PB1) '81~ TRACTOR VER,VWZ(8MA1) '76~'78 TRUCK VTR,VTZ(12PA1) '76~'81 VT(12PA1) '82~ BUS BA,BS(DA640),BU-D(D920H) '76~'79 BU(DH100H) '76~'79 INDUSTRIAL MACHINE (DA220,DA640,8MA1) '78~'81</p> <p style="text-align: center;">Same applications as AVR-615</p>	Now on sale
	0112-0		
	0114-0		
	0134-0		
	0-41000-2390 NK		

<http://www.newera.co.jp/>

New-Era Co., Ltd.



ADDITIONAL APPLICATION

Illustration	Ref. No.	Application	On Sale
<p>SS-1535 12V</p>  	<p>MD618972 ME701462 23343-88V00 31220-68D00 (M371XA0273) N326-18-X10 (M371X64273) ME753151 (M371XA1274)</p> <p>STARTER 12V 1.2KW N318-18-400B (M001T70881A)</p> <p>12V 2.0KW N327-18-400A (M001T74181A) MD312857 (M002T84071) MD315547 (M002T84171) MD314167 (M002T84571)</p> <p>12V 2.2KW MD312858 (M002T87071) MD315548 (M002T87171) MD348221 (M002T88271) ME201650 (M008T75071) ME204424 (M008T75071A) ME202970 (M008T75073) ME204425 (M008T75073A) 1810A050 (M008T75074) ME190889 (M008T75871)</p>	<p>MITSUBISHI DELICA SPACE GEAR PA5W, PB5W (4D56) '94~'03 PC5W '95~'00 PD8W, PE8W (4M40) PF8W DELICA TRUCK P05T, P15T (4D56) '94~'03 DELICA P05T, P15T (4D56) '94~'03 P05V, P15V P05W PD8W, PE8W (4M40) '00~'07 PF8W DELICA CARGO PA5V, PB5V (4D56) '94~'03 PD5V CHALLENGER K94W, K94WG (4D56) '94~'03 MIRAGE CK8A, CM8A (4D68) '95~'98 LANCER CK8A, CM8A (4D68) '95~'98 CK8AR STRADA K74T (4D56) '94~'03 PAJERO V26C, V46V (4M40) '95~'07 V26WG, V46WG V46W V68W, V78W (4M41) '95~'07 V88W, V98W (4M41) '06~ CANTER GUTS FB50A (4M40) '95~'07 FB51A, FD5A (4M40) '95~'00 FB501, FB511 FD501 FB70A,FD70A (4M40) '01~</p> <p>MAZDA SAVANNA RX-7 FC3S, FC3C (13B, 13B RE) '90~'92 LUCE HC3S (13B, 13B RE) '90~'96</p>	<p>MAR.'11</p>
	 <p>(M371XA0273) (M371X64273)</p> <p>(M371XA1274)</p>		