

**2009 NEW MODEL INFORMATION**

**2009/1/14**

# TOKICO

## SHOCK ABSORBERS

※Some model may have different part No. even in same model and year. Please conform OEM No. before place an order.

**NEW STOCK NUMBERS:**

※Start using new stock numbers in 2000 series and E2000 series to 20000 series and E20000 series.

※ストック番号が一部追加で新しくなっています。

現在2000番・E2000番に限り5桁品番が(20000番、E20000番)新設になりましたのでご了承下さい。

**NEW ADDITIONS INFORMATION:**

TOYOTA:COROLLA :U3812

MAZDA:626/MILLENIUM/NEW MILLENIUM :B3277:B3278

MAZDA:626/CAPELLA: FORD:TELSTAR :B3273:B3274:B3275:B3276:B4024:B4025

HONDA:FIT B2286:B2287:B2288:B2289:B2290:B2291:E20012

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

2009/1/14

## TOYOTA

| YEAR | MODEL | FRONT            |         | REAR             |         |
|------|-------|------------------|---------|------------------|---------|
|      |       | R. L. TOKICO. NO | OEM. NO | R. L. TOKICO. NO | OEM. NO |

## CAMRY/VISTA

|           |                          |       |                                                                                                                                                                |       |                                                                                        |
|-----------|--------------------------|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|----------------------------------------------------------------------------------------|
| 90/7-94/6 | SV30,SV32,<br>SV33,VZV31 |       |                                                                                                                                                                | Z3154 | 48530-32220<br>48540-32220                                                             |
| 90/7-94/6 | CV30(DIESEL)             | Z3153 | 48510-32170<br>48520-32170                                                                                                                                     | Z3154 | 48530-32230<br>48540-32230                                                             |
| 94/6-98/6 | SV40,SV41,SV42<br>,CV40  | Z3153 | 48510-39215 48520-39035<br>48510-39225 48520-39045<br>48510-39235 48520-39055<br>48510-39255 48520-39075<br>48510-39265 48520-39085<br>48510-39275 48520-39095 | Z3154 | 48530-39165<br>48530-39175<br>48530-39195<br>48540-39115<br>48540-39125<br>48540-39145 |

## COROLLA

|        |                                                                  |  |  |       |                                                                                        |
|--------|------------------------------------------------------------------|--|--|-------|----------------------------------------------------------------------------------------|
| 01/10- | ZZE122:5Door<br>HB,ZZE122:SED for<br>Australia,built in<br>Japan |  |  | U3812 | 48530-1A520<br>48530-1A700<br>48530-80062<br>48530-1A530<br>48530-80061<br>48530-80101 |
| 02/8-  | ZZE120/121/122/<br>123                                           |  |  | U3812 | 48530-02140<br>48530-02271<br>48530-09D30<br>48530-02141<br>48530-09630<br>48530-09D40 |

## CORONA/CALDINA

|            |                         |       |                                                    |        |                                           |
|------------|-------------------------|-------|----------------------------------------------------|--------|-------------------------------------------|
| 92/11-02/5 | ET196V<br>(1500)        |       |                                                    | E20008 | 48531-80149<br>48531-80212<br>48531-80227 |
| 92/11-96/1 | CT196V<br>(2000 DIESEL) | Z3146 | 48510-20710 48520-20710<br>48510-20760 48520-20760 | E20008 | 48531-80149<br>48531-80212                |
| 96/1-98/5  | CT196V<br>(2000 DIESEL) |       |                                                    | E20008 | 48531-80212<br>48531-80227                |
| 98/6-02/5  | CT197V<br>(2200 DIESEL) |       |                                                    | E20008 | 48531-80227                               |

## COMMUTER

|       |                            |       |                            |       |                            |
|-------|----------------------------|-------|----------------------------|-------|----------------------------|
| 05/1- | KDH2##,LH2##,<br>TRH2##ALL | E3803 | 48511-26650<br>48511-80107 | E3804 | 48531-26860<br>48531-80736 |
|-------|----------------------------|-------|----------------------------|-------|----------------------------|

## NISSAN

| YEAR | MODEL | FRONT            |         | REAR             |         |
|------|-------|------------------|---------|------------------|---------|
|      |       | R. L. TOKICO. NO | OEM. NO | R. L. TOKICO. NO | OEM. NO |

## DATSUN TRUCK/PICK UP

|            |                        |       |                                                                               |      |                                                                   |
|------------|------------------------|-------|-------------------------------------------------------------------------------|------|-------------------------------------------------------------------|
| 98/2- 02/8 | D22<br>(2.4,2.5,TD4WD) | 20005 | 56110-2S600 56110-3S525<br>56110-2S625 56110-3S560<br>56110-2S650 56110-3S570 | 2814 | 56200-35600 56200-35625<br>56210-35625 56210-35626<br>56210-35600 |
|------------|------------------------|-------|-------------------------------------------------------------------------------|------|-------------------------------------------------------------------|

## ISUZU

| YEAR | MODEL | FRONT            |         | REAR             |         |
|------|-------|------------------|---------|------------------|---------|
|      |       | R. L. TOKICO. NO | OEM. NO | R. L. TOKICO. NO | OEM. NO |

## BIG HORN/TROOPER

|       |                                        |       |                                                                             |       |                                                            |
|-------|----------------------------------------|-------|-----------------------------------------------------------------------------|-------|------------------------------------------------------------|
| 98/2- | UBS26/73, V6<br>3.5/3.0D, 4WD<br>WAGON | E3735 | 9-87043-816-2 8-97113-500-2<br>9-87043-816-3 8-97113-500-3<br>9-87043-816-4 | E3793 | 8-97043-817-1 8-97043-817-2<br>8-97043-828-1 8-97043-818-2 |
|-------|----------------------------------------|-------|-----------------------------------------------------------------------------|-------|------------------------------------------------------------|

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

## SUZUKI

| YEAR |            | MODEL   |  | FRONT |            | REAR    |  |
|------|------------|---------|--|-------|------------|---------|--|
| R. L | TOKICO. NO | OEM. NO |  | R. L  | TOKICO. NO | OEM. NO |  |

### ALTO/SH410

|       |             |  |  |  |       |                                           |
|-------|-------------|--|--|--|-------|-------------------------------------------|
| 98/8- | HA11/12/ 22 |  |  |  | E1182 | 41800-76G00<br>41800-77G00<br>41800-78G00 |
|-------|-------------|--|--|--|-------|-------------------------------------------|

### GRAND VITARA XL-7/GRAND ESCUDO

|       |                                         |  |  |  |       |             |
|-------|-----------------------------------------|--|--|--|-------|-------------|
| 01/7- | H27A, 2.7V6<br>4WD WAGON,<br>ALL MODELS |  |  |  | E2998 | 41700-52D01 |
|-------|-----------------------------------------|--|--|--|-------|-------------|

## MAZDA

| YEAR | MODEL | FRONT |            | REAR    |      |
|------|-------|-------|------------|---------|------|
|      |       | R. L  | TOKICO. NO | OEM. NO | R. L |

### 323/FAMILIA/FORD LASER

|           |                        |  |  |    |       |                                            |                             |
|-----------|------------------------|--|--|----|-------|--------------------------------------------|-----------------------------|
| 89/6-94/8 | BG8#F/H 4WD<br>3/4DOOR |  |  | RR | A2284 | B528-28-700<br>B531-28-700A<br>B698-28-700 | B530-28-700<br>B531-28-700B |
|           |                        |  |  | RL | A2285 | B528-28-900<br>B531-28-900A<br>B698-28-900 | B530-28-900<br>B531-28-900B |

### PREMACY

|       |                             |  |  |    |       |                                                          |                                                |
|-------|-----------------------------|--|--|----|-------|----------------------------------------------------------|------------------------------------------------|
| 99/7- | CP#(1.9, 2.0,<br>2.0TD 2WD) |  |  | RR | B3269 | C100-28-700<br>C145-28-700<br>CB01-28-700<br>CB80-28-700 | C100-28-700B<br>CB01-28-700A<br>C145-28-700AL3 |
|       |                             |  |  | RL | B3270 | C100-28-900<br>C145-28-900<br>CB01-28-900                | C100-28-900B<br>CB01-28-900A<br>C145-28-700AL3 |

### 626 MILLENIUM/NEW MILLENIUM

|       |                      |       |             |  |       |             |
|-------|----------------------|-------|-------------|--|-------|-------------|
| 98-05 | FOR COLOMBIA<br>2.0L | B3277 | GJ3M-34-700 |  | B3196 | GJ1M-28-700 |
|       |                      | B3278 | GJ3M-34-900 |  | B3197 | GJ1M-28-900 |

### 626 (CAPELLA) /FORD TELSTAR

|            |                                                                                               |       |                              |  |       |              |
|------------|-----------------------------------------------------------------------------------------------|-------|------------------------------|--|-------|--------------|
| 97/5-02/5  | GF1<br>(1.8,2.0,2.0HP,<br>2.0TD,2.5<br>4SD/5HD<br>STANDARD SUS)                               | B3273 | G14H-34-700A<br>GE4T-34-700A |  | B3196 | GE4T-28-700A |
|            |                                                                                               | B3274 | G14H-34-900A<br>GE4T-34-900A |  | B3197 | GE4T-28-900A |
| 97/5-02/5  | GF1 WITH<br>HEIGHTENING<br>ROAD<br>CLEARANCE                                                  | B3275 | G14F-34-700A<br>GE4V-34-700A |  | B3196 | GE4V-28-700A |
|            |                                                                                               | B3276 | G14F-34-900A<br>GE4V-34-900A |  | B3197 | GE4V-28-900A |
| 97/10-02/5 | GW1<br>(1.8,2.0,2.0HP,<br>2.0TD,2.5ESTATE<br>/ WAGON)<br>EXCEPT SELF-<br>LEVELING REAR<br>SUS | B3273 | G14V-34-700A<br>GF3H-34-700A |  | B4024 | GF3H-28-700A |
|            |                                                                                               | B3274 | G14V-34-900A<br>GF3H-34-900A |  | B4025 | GF3H-28-900A |
| 97/10-02/5 | GW1 WITH<br>HEIGHTENING<br>ROAD<br>CLEARANCE<br>EXCEPT SLF-<br>LEVELING REAR<br>SUS           | B3275 | G15C-34-700A<br>GF3J-34-700A |  | B4024 | GF3J-28-700B |
|            |                                                                                               | B3276 | G15C-34-900A<br>GF3J-34-900A |  | B4025 | GF3J-28-900B |

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

| YEAR | MODEL | FRONT |            | REAR |            |
|------|-------|-------|------------|------|------------|
|      |       | R. L  | TOKICO. NO | R. L | TOKICO. NO |

## MAZDA FIGHTER (BT50) / FORD RANGER

|           |                                |  |       |                             |  |       |                                                            |
|-----------|--------------------------------|--|-------|-----------------------------|--|-------|------------------------------------------------------------|
| 97-02     | J97 A/C(4X2)                   |  | 2794  | UH71-34-70X                 |  | 2795  | UH71-28-700                                                |
| 97-02     | J97 A/C(4X4)                   |  | 3586  | UH74-34-70X                 |  | 3572  | UH74-28-700                                                |
| 02/6-06/2 | J97 PT(4X2)                    |  | E2794 | UH72-34-700A                |  | E2795 | UH72-28-700                                                |
| 02/6-06/2 | J97 PT(4X4)                    |  | E3586 | UH75-34-700<br>UH75-34-700A |  | E3572 | UH75-28-700                                                |
| 06/3-     | J97 MU(4X2)                    |  | E4121 | UR58-34-70X<br>UR58-34-700B |  | E4122 | UR58-28-700<br>UR58-28-700C<br>UR70-28-700<br>UR70-28-700A |
| 06/3-     | J97 MU(4X4)<br>J90U(U268)(4X4) |  | E4124 | UR61-34-70XC<br>UA3J-34-70X |  | E4125 | UR61-28-700C<br>UA3J-28-700A                               |

| FORD |       | FRONT |            | REAR |            |
|------|-------|-------|------------|------|------------|
| YEAR | MODEL | R. L  | TOKICO. NO | R. L | TOKICO. NO |

## EVEREST

|            |                            |  |       |              |  |       |              |
|------------|----------------------------|--|-------|--------------|--|-------|--------------|
| 03/4-06/2  | J90F,<br>J90U(U268)        |  | E4123 | UP20-34-700A |  | E4111 | UP21-28-700C |
| 06/3-07/10 | J97MU4X4,<br>J90U(U268)4X4 |  | E4124 | UR61-34-70XC |  | E4125 | UR61-28-700C |
| 07/11-     | J90F,<br>J90U(U268)        |  | E4123 | UP20-34-700A |  | E4126 | UV9K-28-700  |

| MITSUBISHI |       | FRONT |            | REAR |            |
|------------|-------|-------|------------|------|------------|
| YEAR       | MODEL | R. L  | TOKICO. NO | R. L | TOKICO. NO |

## LANCER (MADE IN THAILAND ONLY)

|       |            |    |       |            |       |           |
|-------|------------|----|-------|------------|-------|-----------|
| 96-99 | CK2A, 1.5L | FR | A2271 | MR297576T  | Q2947 | MR244217T |
|       |            | FL | A2272 | MR297575T  |       |           |
| 96-99 | CK5A, 1.8L | FR | A2227 | MR316070MT | Q2947 | MR244217T |
|       |            | FL | A2228 | MR316069MT |       |           |

※This Lancer doesn't fit to Japan made or OEM No without "T"

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

## HONDA

| YEAR | MODEL | FRONT |            | REAR |            |
|------|-------|-------|------------|------|------------|
|      |       | R. L  | TOKICO. NO | R. L | TOKICO. NO |

### ACCORD COUPE

|         |                                   |  |       |                                |       |               |
|---------|-----------------------------------|--|-------|--------------------------------|-------|---------------|
| 90/4-96 | CB6(2.0SI-EXCL)<br>CB7(2.2I EXCL) |  | U3714 | 51605-SM1-A02<br>51606-SM1-A02 | U2896 | 52611-SM1-A22 |
|---------|-----------------------------------|--|-------|--------------------------------|-------|---------------|

### ACCORD

|            |                                                                                           |  |                     |                                                                                                                                                                                                                                                      |                     |                                                                                                                     |
|------------|-------------------------------------------------------------------------------------------|--|---------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------------------------------------|
| 89/9-93/9  | CB1,CB2,CB3(2.0EXL)<br>CB3(2.0SI,2.0EXL-I,<br>2.0SI-T)CB4(2.0EXL),<br>CB4(2.0EXL-I,2.0SI) |  | U3737               | 51605-SM4-E02<br>51606-SM4-E02<br>51605-SM4-J02<br>51606-SM4-J02                                                                                                                                                                                     | U2896               | 52611-SM4-014<br>52611-SM4-913<br>52611-SM4-961<br>52611-SM4-J61                                                    |
| 89/9-93/10 | CB8/9<br>(USA WAGON)                                                                      |  | U3737<br>↓<br>U3714 | 51605-SM4-305<br>51606-SM4-305                                                                                                                                                                                                                       | U2896<br>↓<br>U2896 | 52611-SM4-305                                                                                                       |
| 89-96      | CB#,CC#,CE#                                                                               |  | U3737               | 51601-SM4-E24 51605-SN7-E02<br>51602-SM4-E24 51606-S37-G00<br>51605-S37-G00 51606-SM1-A02<br>51605-SM1-A02 51606-SM4-305<br>51605-SM4-J02 51606-SM4-E02<br>51605-SM4-305 51606-SM4-J02<br>51605-SM4-E02 51606-SN7-E01<br>51605-SN7-E01 51606-SN7-E02 | U2896               | 52611-S37-G00<br>52611-SM1-A22<br>52611-SM4-014<br>52611-SM4-913<br>52611-SM4-Y02<br>52611-SN7-E01<br>52611-SN7-E02 |
| 97/9-      | CF3/4/6(1.8I/<br>2.0I/2.2I<br>SED/WAGON)                                                  |  | U3807               | 51605-S0A-922<br>51605-S0A-J12                                                                                                                                                                                                                       | U3808               | 52611-S0A-923<br>52611-S0A-J02<br>52611-S0A-J12                                                                     |
| 98/10-     | CG7/8/9,CH1<br>(1.6I/1.8I/2.0I/<br>2.2I SED)                                              |  | U3807               | 51605-S1A-E02<br>51605-S1A-G21                                                                                                                                                                                                                       | U3808               | 52611-S1A-E01<br>52611-S1A-G21                                                                                      |
| 03/02-     | CL7/8/9,CM#                                                                               |  | U3781               | 51605-SDA-Y03 51605-SEB-J02<br>51605-SDB-A04 51605-SED-903<br>51605-SDB-Y04 51605-SED-J01<br>51605-SEA-902 51605-SEE-J01<br>51605-SEA-E02                                                                                                            | U3806               | 52610-SDA-A02<br>52611-SDA-A02<br>52611-SDB-A02                                                                     |

※Accord USA wagon CB8/9 doesn't fit U3737 but U3714

| YEAR | MODEL | FRONT |            | REAR |            |
|------|-------|-------|------------|------|------------|
|      |       | R. L  | TOKICO. NO | R. L | TOKICO. NO |

### ACCORD/VIGOR

|       |                                            |  |       |                                                                                                                                                                          |       |                                |
|-------|--------------------------------------------|--|-------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--------------------------------|
| 03/2- | CL#(2.0L 1,2.4L<br>1,2.2L CDTi)            |  | U3781 | 51605-SDA-Y03 51605-SED-903<br>51605-SDB-A04 51605-SED-E12<br>51605-SDB-Y04 51605-SED-J01<br>51605-SEA-902 51605-SEE-J01<br>51605-SEA-E02 51605-SEF-E03<br>51605-SEB-J02 | U3809 | 52611-SEA-E03<br>52611-SEF-E02 |
| 03/2- | CM1(2.0L)/CM2<br>(2.4L)/CN2<br>(2.2L CDTi) |  | U3781 | 51605-SDA-Y03 51605-SED-903<br>51605-SDB-A04 51605-SED-E12<br>51605-SDB-Y04 51605-SED-J01<br>51605-SEA-902 51605-SEE-J01<br>51605-SEA-E02 51605-SEF-E03<br>51605-SEB-J02 |       |                                |

### FIT/JAZZ

|       |                            |    |       |                                                                                           |        |                                 |
|-------|----------------------------|----|-------|-------------------------------------------------------------------------------------------|--------|---------------------------------|
| 01/6- | GD1(1300)<br>GD2(1300 4WD) | FR | B2288 | 51601-SAA-G02 51601-SAA-G12<br>51601-SAA-J25 51605-SAA-033<br>56101-SAA-J15 51605-SAA-G02 | E20012 | 52610-SAA-G02                   |
|       |                            | FL | B2289 | 51602-SAA-G02 51602-SAA-G12<br>51602-SAA-J25 51606-SAA-033<br>56102-SAA-J15 51606-SAA-G02 |        |                                 |
| 02/9- | GD1(1300)<br>GD3(1500)     | FR | B2290 | 51601-SAA-J51 51605-SAA-J51<br>51601-SAA-J61 51605-SAG-C02<br>56105-SAA-004               | E20012 | 52610-SAA-E03<br>52610-SAG-C020 |
|       |                            | FL | B2291 | 51602-SAA-J51 51606-SAA-J51<br>51602-SAA-J61<br>56106-SAA-004<br>51605-SAE-T02            |        |                                 |
| 04-06 | GD1/GD3<br>FOR THAILAND    | R  | B2286 |                                                                                           |        |                                 |
|       |                            | L  | B2287 | 51606-SAE-T02                                                                             |        |                                 |

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

## DAIHATSU

| YEAR | MODEL | FRONT |            | REAR |            |
|------|-------|-------|------------|------|------------|
|      |       | R. L  | TOKICO. NO | R. L | TOKICO. NO |

## TERIOS

|            |                                                                         |  |  |  |        |             |
|------------|-------------------------------------------------------------------------|--|--|--|--------|-------------|
| 97/3-      | J100(2WD) INCL.<br>WITH ABS                                             |  |  |  | E1216  | 48530-87401 |
| 97/3-98/9  | J100G<br>(1300,4WD)                                                     |  |  |  | E1216  | 48530-87401 |
| 98/9-00/5  |                                                                         |  |  |  | E20011 | 48530-87409 |
| 00/5-05/12 | J102G<br>(1300, 4WD)<br>CL, CX AERO<br>PACK, CUSTOM<br>MEMORIAL<br>PACK |  |  |  | E20009 | 48530-87404 |
| 01/12-03/8 |                                                                         |  |  |  | E20010 | 48530-87407 |
| 00/5-05/12 |                                                                         |  |  |  | E20010 | 48530-87407 |
| 00/5-05/12 | J122G<br>(1300)                                                         |  |  |  | E20010 | 48530-87407 |

**NEW MODELS FOR INDONESSIAN MARKET.  
PLEASE CHECK THE COMPATIBILITY FOR OTHER COUNTRIES**

**TOYOTA**

| YEAR |            | MODEL   |  | FRONT |            | REAR    |  |
|------|------------|---------|--|-------|------------|---------|--|
| R. L | TOKICO. NO | OEM. NO |  | R. L  | TOKICO. NO | OEM. NO |  |

**KIJANG CAPSUL**

|     |  |  |      |                            |  |       |                            |
|-----|--|--|------|----------------------------|--|-------|----------------------------|
| 97- |  |  | 2612 | 48500-0B020<br>48500-09020 |  | 20002 | 48531-0B090<br>48531-09170 |
|-----|--|--|------|----------------------------|--|-------|----------------------------|

**KIJANG INNOVA**

|     |  |    |       |             |  |       |             |
|-----|--|----|-------|-------------|--|-------|-------------|
| 04- |  | FR | U3773 | 48510-0K080 |  | E3796 | 48531-0K210 |
|     |  | FL | U3774 | 48520-0K080 |  |       |             |

**KIJANG GRAND EXTRA**

|  |  |  |      |                            |  |       |                            |
|--|--|--|------|----------------------------|--|-------|----------------------------|
|  |  |  | 2612 | 48500-0B020<br>48500-09020 |  | 20002 | 48531-0B090<br>48531-09170 |
|--|--|--|------|----------------------------|--|-------|----------------------------|

**AVANZA**

|     |  |  |  |  |  |       |             |
|-----|--|--|--|--|--|-------|-------------|
| 03- |  |  |  |  |  | E2999 | 48531-BZ090 |
|-----|--|--|--|--|--|-------|-------------|

**DAIHATSU**

| YEAR | MODEL | FRONT |            |         | REAR |            |         |
|------|-------|-------|------------|---------|------|------------|---------|
|      |       | R. L  | TOKICO. NO | OEM. NO | R. L | TOKICO. NO | OEM. NO |

**ZEBRA**

|     |           |  |                  |                                               |  |      |                                |
|-----|-----------|--|------------------|-----------------------------------------------|--|------|--------------------------------|
| 87- | S-88/S-89 |  | <del>S1120</del> | 48511-00002-001<br>48510-87545<br>48520-87542 |  | 2842 | 48530-87535-001<br>48530-87535 |
|-----|-----------|--|------------------|-----------------------------------------------|--|------|--------------------------------|

**ESPASS**

|     |      |  |                  |             |  |      |             |
|-----|------|--|------------------|-------------|--|------|-------------|
| 95- | S-91 |  | S1119            | 48511-00001 |  | 2842 | 48530-87535 |
|     | S-92 |  | <del>S1120</del> | 48511-00002 |  | 2842 | 48530-87535 |

※S1120 is stopped development

**F-70/TAFT GT**

(FRONT AND REAR ARE SAME STOCK No)

|     |  |  |        |                            |  |        |                            |
|-----|--|--|--------|----------------------------|--|--------|----------------------------|
| 84- |  |  | E20003 | 48510-87606<br>48510-87680 |  | E20003 | 48530-87612<br>48530-87680 |
|-----|--|--|--------|----------------------------|--|--------|----------------------------|

**TARUNA**

|     |  |  |  |  |  |       |             |
|-----|--|--|--|--|--|-------|-------------|
| 99- |  |  |  |  |  | E3802 | 48530-87Z13 |
|-----|--|--|--|--|--|-------|-------------|

**XENIA**

|     |  |  |  |  |  |       |             |
|-----|--|--|--|--|--|-------|-------------|
| 03- |  |  |  |  |  | E2999 | 48531-BZ090 |
|-----|--|--|--|--|--|-------|-------------|

# TOKICO SHOCK ABSORBERS NEW MODEL INFORMATION

## SUZUKI

| YEAR | MODEL | FRONT |            |         | REAR |            |         |
|------|-------|-------|------------|---------|------|------------|---------|
|      |       | R. L  | TOKICO. NO | OEM. NO | R. L | TOKICO. NO | OEM. NO |

### FUTURA

|     |  |  |       |                                                |  |      |                                 |
|-----|--|--|-------|------------------------------------------------|--|------|---------------------------------|
| 91- |  |  | S1118 | 41601-77511-L000<br>41601-77510<br>41602-77510 |  | 1218 | 41700-77500-L000<br>41700-77500 |
|-----|--|--|-------|------------------------------------------------|--|------|---------------------------------|

### CARRY

|       |        |  |       |                                                |  |      |                                 |
|-------|--------|--|-------|------------------------------------------------|--|------|---------------------------------|
| 84-88 | ST-100 |  | S1117 | 41601-77310-L000<br>41601-77310<br>41602-77310 |  | 1219 | 41700-77320-L000<br>41700-61010 |
|-------|--------|--|-------|------------------------------------------------|--|------|---------------------------------|

### ESCUDE

|  |  |  |  |  |  |       |             |
|--|--|--|--|--|--|-------|-------------|
|  |  |  |  |  |  | E2916 | 41700-56B00 |
|--|--|--|--|--|--|-------|-------------|

### APV

|     |  |  |  |  |  |       |             |
|-----|--|--|--|--|--|-------|-------------|
| 04- |  |  |  |  |  | 20004 | 41700-61J10 |
|-----|--|--|--|--|--|-------|-------------|

## MITSUBISHI

| YEAR | MODEL | FRONT |            | REAR    |      |
|------|-------|-------|------------|---------|------|
|      |       | R. L  | TOKICO. NO | OEM. NO | R. L |

### L300

|  |  |  |      |                      |  |      |                      |
|--|--|--|------|----------------------|--|------|----------------------|
|  |  |  | 3228 | MT141246<br>MB175562 |  | 2048 | MB110774<br>MB111056 |
|--|--|--|------|----------------------|--|------|----------------------|

### COLT

|     |        |  |       |                                  |  |      |          |
|-----|--------|--|-------|----------------------------------|--|------|----------|
| 91- | T120SS |  | S1118 | MZS41029<br>MZS41002<br>MZS41004 |  | 2992 | MZS41024 |
|-----|--------|--|-------|----------------------------------|--|------|----------|

## ISUZU

| 1992 | YEAR | MODEL | FRONT      |         |      | REAR       |         |  |
|------|------|-------|------------|---------|------|------------|---------|--|
| R. L |      |       | TOKICO. NO | OEM. NO | R. L | TOKICO. NO | OEM. NO |  |
|      |      |       |            |         |      |            |         |  |

### PANTHER

|  |           |  |       |                              |  |        |                              |
|--|-----------|--|-------|------------------------------|--|--------|------------------------------|
|  | C190/C233 |  | E2618 | 8-97955-175-0<br>8-97014-042 |  | E20001 | 8-97955-176-0<br>8-97014-043 |
|  | TBR541    |  | E2618 | 8-97956-186                  |  | E20001 | 8-97956-187                  |